

FIG. 2 (B)





FIG. 3 (B)



3/12

FIG. 4





FIG. 5



4/12

FIG. 6




FIG. 7 (A)






FIG. 7 (B)



5/12

FIG. 8 (A)




BUBBLE-FORMING CAPACITY OF THE ORIFICE

5/1/12


09/529257

FIG. 8 (B)




BUBBLE-FORMING CAPACITY OF THE ORIFICE

FIG. 9 (A)



6/1/12


FIG. 9 (B)



JET SPEED AT THE NOZZLE AND THE PRESSURE LOSS (ORIFICE $\phi = 100\text{mm}$)

7/12

FIG. 10



8/12

FIG. 11 (A)




FIG. 11 (B)








FIG. 12





11/12

FIG. 14



12/12

FIG. 15

